



DEPARTMENT OF  
WATER RESOURCES

# WEST SACRAMENTO AREA *Fact Sheet* Site 56.1

Critical Levee Erosion Site

## Emergency Levee Repairs

### Location

River: Sacramento River

River Mile: 56.1

Longitude/Latitude:

38.542961/-121.512585

Nearest Impact Area:

West Sacramento

County: Yolo

Bank: Right

### Type of Damage

Bank erosion

### Length of Repair


900 feet (approximate)

### Repair Type

Rock slope protection

### Lead Agency

Department of Water Resources



**For further information, please contact:**

**Elizabeth Scott**  
**DWR Public Affairs Office**  
**(916) 835-5344**  
**[leveerepair@water.ca.gov](mailto:leveerepair@water.ca.gov)**

DEPARTMENT OF WATER RESOURCES  
PO Box 942836, Sacramento, CA 94236

**[www.levees.water.ca.gov](http://www.levees.water.ca.gov)**

